

**To:** Sorrenson - DNR, Allen[allen.sorenson@state.co.us]  
**From:** Way, Steven  
**Sent:** Mon 3/24/2014 10:45:21 PM  
**Subject:** FW: Gold King Phase II - estimates for portal work  
Gold King Rehab Phase II.pdf

Allen,

Just thought I would have you look these over and lend your opinion.

Thanks,

STeve

Federal On-Scene Coordinator

Emergency Response Program (8EPR-ER)  
US EPA Region 8  
1595 Wynkoop Street  
Denver, CO 80202-1129

Office: 303-312-6723

**From:** Todd Hennis [mailto: ] **Personal Email/Ex. 6**  
**Sent:** Monday, March 17, 2014 2:06 PM  
**To:** Way, Steven  
**Subject:** Fw: Gold King Phase II

Steve-

Phase 2 of the Gold King reopening- this assumes 70 feet of timbering to get back past the tunnel intersection with the older portal drift. Mr. Maisel has advised that timbering elsewhere should run in line with this estimate.

For San Juan Corp.,

Todd C. Hennis. Pres.

On Monday, March 17, 2014 1:45 PM, Pete Maisel <[pmaisel@thebent.com](mailto:pmaisel@thebent.com)> wrote:

Pete Maisel

Maisel Excavation, LLC

[www.maiselx.com](http://www.maiselx.com)

[pete@maiselx.com](mailto:pete@maiselx.com)

970.759.9291

---

This email is free from viruses and malware because [avast! Antivirus](#) protection is active.